Er Buch

(Page 1 of 2)

State of California AIR RESOURCES BOARD

EXECUTIVE ORDER A-14-193 Relating to Certification of New Motor Vehicles

TOYOTA MOTOR CORPORATION

Pursuant to the authority vested in the Air Resources Board by the Health and Safety Code, Division 26, Part 5, Chapter 2; and

Pursuant to the authority vested in the undersigned by Health and Safety Code Sections 39515 and 39516 and Executive Orders G-45-3 and G-45-4:

IT IS ORDERED AND RESOLVED: That 1992 model Toyota Motor Corporation exhaust emission control systems are certified as described below for passenger cars:

Fuel Type: Gasoline

Engine Family: NTY1.5V5FCC4 Displacement: 1.5 Liters (89 Cu. In.)

Exhaust Emission Control Systems and Special Features:

Three-Way Catalyst Oxygen Sensor Exhaust Gas Recirculation Multipoint Electronic Fuel Injection

Vehicle models, transmissions, engine codes and evaporative emission control families are listed on attachments.

The emission standards for this engine family in grams per mile are:

<u>Hydrocarbons</u>	<u>Carbon Monoxide</u>	<u>Nitrogen Oxides</u>
0.39	7.0	0.4

The certification emission values for this engine family in grams per mile are:

<u>Hydrocarbons</u>	<u>Carbon Monoxide</u>	<u>Nitrogen Oxides</u>
0.14	1.2	0.1

BE IT FURTHER RESOLVED: That the listed vehicle models also comply with "California Evaporative Emission Standards and Test Procedures for 1978 and Subsequent Model Gasoline-Powered Motor Vehicles".

BE IT FURTHER RESOLVED: That the listed vehicle models also comply with the Board's "Specifications for Fill Pipes and Openings of Motor Vehicle Fuel Tanks" (Title 13, California Code of Regulations, Section 2290) for the aforementioned model-year.

BE IT FURTHER RESOLVED: That the listed vehicle models also comply with the Board's high altitude requirements and highway emission standards as stipulated in "California Exhaust Emission Standards and Test Procedures for 1988 and Subsequent Model Passenger Cars, Light-Duty Trucks, and Medium-Duty Vehicles".

BE IT FURTHER RESOLVED: That the listed vehicle models also comply with the "California Motor Vehicle Emission Control Label Specifications" (Title 13, California Code of Regulations, Section 1965) for the aforementioned model year.

BE IT FURTHER RESOLVED: That the vehicle models listed also comply with the requirements of the "Malfunction and Diagnostic System for 1988 and Subsequent Model Year[s]..." (Title 13, California Code of Regulations, Section 1968) for the aforementioned model year.

BE IT FURTHER RESOLVED: That for the listed vehicles, the manufacturer has submitted and the Executive Officer hereby approves the materials to demonstrate certification compliance with the Board's emission control system warranty provisions (California Health and Safety Code Section 43205).

Vehicles certified under this Executive Order must conform to all applicable California emission regulations.

The Bureau of Automotive Repair will be notified by copy of this order and attachment.

Executed at El Monte, California this 25 day of July, 1991.

R. B. Summerfield

Assistant Division Chief Mobile Source Division 0

1992 AIR RESOURCES BOARD SUPPLEMENTAL DATA SHEET

							Page
Manufacti	urer	TOYOTA	·		Engine fam	ily <u>nt</u>	Y1.5V5FCC4
Passenger Cars x Light-Duty Trucks Medium-Duty Vehicles Puel Type Gasoline							
Engine Config. L-4 Liter (CID) 1.5 (88.9) Evap.Family EV-E							
Emission Control System & Special Features MPI + EGR + O2S + TWC (Use abbreviation per SAE J1930 Jun88)							
Engine :	Front <u>x</u> Mid	Rear		Drive:	FWD x RWD	4WD-FT	_ 4WD-PT
Certification std.: 0.4 NOx							
Engine	Veh. Models	Trans.	BTW	RLHP	Ign. System	EGR	Catalyst
	(If Coded see				(PCME/PROM)		
	attachmt.)	A-Auto				Part No.	Part No.
std.)	attachmt.)	M-Man.		Ĺ		<u> </u>	
1	BL42L-ADKBBA	M4	2,250	6.4	89661-16081	25620-11100	18450-16420*1
	-admrea	M5	2,375	6.9	1	1	(B07)*3
	-armdea			1	1	1	18450-0w010 ^{*2}
	-AEMREA	<u> </u>	1	<u> </u>	1	1	(B97)*3
2	EL42L-ADKBEA	•	2,375	6.4	1	1	
	-admrea	M5	-	6.9	ļ	!	
	-AEMDEA	!	İ	!	ļ	!	
3	-AEMREA	1364	2 225	12.0			
3	EL42L-ADKBEA	M4 M5	2,375	•	1	<u> </u>	
	-ADMREA	ו כתן	i :	7.6] 1	{ ≟	
	-AEMDEA	l i	1 ?	l i]]	[]	} I
4	-AEMREA EL42L-ADKBEA	M4	2,375	7 0] 	!]
•	-ADMREA	M5	12,313	7.6	1	1 1]]
	-AEMREA	1	! !	' · · •	İ	! })
	-aemdea	1	2,500	ì	i	1	! }
5	EL42L-ADHREA	la3	2,375		i	25620-11090	;
-	-AEHDEA	1	1	i	<u> </u>	1	
	-aehrea	i	İ	j	i	i	
6	EL42L-ADHREA	i	2,375	16.9	i	ì	
	-aehrea	i			i	ĺ	
	-aehdea	j	2,500	<u>i</u>	İ	j	
7	BL42L-ADHREA	A3	2,375	7.6	1]	
	-aehdea	!	2,500	ļ	!	!	
	-AEHREA	Į.			!	!	
8	EL42L-ADHREA	ļ.	2.500	7.6	ļ		
	-aehdea	ļ	Į.	ļ	ļ	I	
	-aehrea	1	l	L	1	1	L

Page : 17.11-7

Issued : 05/24/91

17.11.00

 $\langle T_{i,j}\rangle$

Comments: Please refer to manufacturer's HP list for correct dyno test HP setting based on model and equipment.

Note *1: 18450-16420: Maker; TOYOTA MOTOR CORPORATION

*2 : 18450-0W010 : Maker ; TABC, Inc.

*3 : Parenthetical information represents identifying marks found

on production parts.

VEHICLE MODELS :

Tercel					
EL42L-ADKBEA	EL42L-ADHREA				
-admrea	-aehdea				
-aemdea	-aehrea				
-aemrea					

Page : 17.11-8

Issued: 05/24/91